

TURBINE T501LK CON LIEVI DIFETTI ESTETICI

T501LK turbines with minor aesthetic flaws

S.N. 2210057



S.N. 2210019



S.N. 2210058



S.N. 2210049



S.N. 2210055



S.N. 2210054



S.N. 2210046



S.N. 2210053



S.N. 2210016



S.N. 2210047




S.N. 2210050



S.N. 2210056



S.N. 2210012



S.N. 2210045

